

30 January 1976

SERVICE BULLETIN - 104

This service bulletin applies to all Raven Rally (RX-6) Hot Air Balloons certified in all categories.

All flights in Rally hot air balloons should be suspended when temperatures are below 40°F until factory supplied gondola reinforcing inserts are installed. Failure to heed this warning could result in polyethylene liner cracking during landing and could cause injuries. The problem has existed only at cold temperatures. There is no reason to curtail flights in temperatures above 40°F.

Raven will install the liner at no charge to the owner, in conjunction with an annual inspection performed at the factory. If an annual is not currently due, or you don't want to send it to the factory, we will send you the liners along with installation instructions. A log book entry must be made and signed by an authorized personnel.

To obtain the liners for your gondola, or if you have questions, please write or call:

Orv Olivier  
Raven Industries, Inc.  
P.O. Box 1007  
Sioux Falls, South Dakota 57105  
605/336-2750

It is quite probable that you will be receiving an Airworthiness Directive from the Federal Aviation Administration requiring the installation of the reinforcing liner.

**RAVEN**

industries, inc.

BOX 1007 SIOUX FALLS SOUTH DAKOTA 57101 PHONE 605-336-2750

SERVICE BULLETIN 104

When the requirements of Raven Service Bulletin 104 have been completed, please fill in the information requested below and return to Raven.

Serial Number: RX6-

Registration Number: N.

Owners Name: \_\_\_\_\_

Address: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_ Zip.

Number of Hours on Aircraft When Work Was Completed: \_\_\_\_\_

Date Work Completed: \_\_\_\_\_

Signature of Person Performing the Work: \_\_\_\_\_

\_\_\_\_\_