

76-03-04 - Gondola liner

AEROSTAR-RAVEN:

Category - Airframe

Effective Date - 02/13/1976 Recurring - No

Supersedes - N/A Superseded by - N/A

RAVEN INDUSTRIES INC:

Amendment 39-2508.

Applies to Raven Model RX-6 hot air balloons certificated in all categories.

Compliance required before further flight.

To prevent cracking and breaking of the polyethylene gondola liner, accomplish the following:

Install a placard on the instrument panel in clear view of the pilot, stating, "Operation limited to ground surface temperatures of 40 degrees F and above".

The hot air balloon may be operated only when ground surface temperature is at or above 40 degrees F until modifications to reinforce the gondola liner, be made available by Raven Industries, Inc., are installed.

This amendment becomes effective February 13, 1976.
